

**ПЕРЕЧЕНЬ
координат характерных точек устанавливаемых красных линий**

Номер точки	X	Y
1	2	3
Контур 1		
1	90775,84	115234,44
2	90781,51	115237,51
3	90788,17	115241,12
4	90791,20	115251,49
5	90784,89	115264,61
6	90781,05	115272,58
7	90740,20	115357,39
8	90735,61	115366,91
9	90679,87	115482,64
10	90669,75	115503,66
11	90683,32	115509,85
12	90683,83	115510,15
13	90682,09	115514,10
14	90682,07	115514,14
15	90682,11	115514,17
16	90677,00	115525,00
17	90676,54	115526,00
18	90676,45	115526,19
19	90676,05	115526,01
20	90672,58	115533,01
21	90670,51	115537,19
22	90661,75	115554,92
23	90661,04	115554,98
24	90655,28	115555,35
25	90647,20	115555,89
26	90605,33	115559,21
27	90594,60	115565,81
28	90581,41	115572,77
29	90566,72	115579,28
30	90566,69	115596,06
31	90566,68	115606,83
32	90566,64	115633,67
33	90580,90	115633,40
34	90598,55	115632,36
35	90613,37	115630,66
36	90636,18	115628,69

1	2	3
37	90649,36	115618,89
38	90653,57	115615,76
39	90660,23	115610,82
40	90681,11	115567,72
41	90682,35	115567,32
42	90685,10	115562,16
43	90685,80	115561,12
44	90699,14	115533,47
45	90706,70	115519,11
46	90716,68	115498,40
47	90723,81	115483,60
48	90769,68	115388,36
49	90771,65	115384,27
50	90772,56	115382,38
51	90774,14	115379,10
52	90820,93	115281,96
53	90824,19	115275,19
54	90828,35	115266,55
55	90833,17	115265,75
56	90836,27	115267,41
57	90843,90	115271,52
58	90850,82	115275,24
59	90862,57	115281,56
60	90869,64	115268,34
61	90874,33	115259,56
62	90881,74	115245,69
63	90881,82	115245,54